HANCOCK MEETINGHOUSE

Hancock, New Hampshire

Historic Building Assessment

with

Preservation Guidelines

Prepared by

Elizabeth Durfee Hengen
Preservation Consultant
&
Stephen Bedard
Bedard Preservation & Restoration

for

Town of Hancock
August 2011

HANCOCK MEETINGHOUSE

Historic Building Assessment with Preservation Guidelines

TABLE OF CONTENTS

Introduction 1

History and Evolution of the Meetinghouse 2

Hancock Meetinghouse Timeline 18

Sources Consulted 20

Architectural Description & Character-Defining Features 22

- Site 22
- Exterior 22
- Interior: First Floor 31
- Interior: Second Floor 37
- Cellar 41
- Horse Sheds 42

Existing Conditions Survey 43

- Site 43
- Foundation, Posts, Cellar and Furnaces 43
- Floor Framing under the Town Hall 46
- Clapboards and Trim 47
- Windows and Doors 47
- Roof Covering 49
- Roof Framing System 50
- Chimneys 51
- Timber Framing 52
- Tower 53
- ADA Access 59
- Interior Spaces 59
- Existing Insulation 59
- Electrical and Alarm Systems 60

Preservation Guidelines & Estimated Costs for Needed Work 61
Overall Approach to Treatment 61
Site 61
Foundation, Posts and Cellar 62
Clapboards and Trim 63
Doors, Windows and Storm Windows 63
Roof 64
Chimneys 65
Tower 65
ADA Access 66
Insulation 67
Electrical and Alarm Systems 68
General Interior Work 68
Recommended Work Phases with Estimated Costs 69
Appendices
A: Secretary of Interior's Standards for Preservation 71
B: Measured Drawings (annotated) 72
C: Articles of Agreement (1851) 83
D: Article on 1888 Renovations 85